



BJT



11/29/16
Pg 26



H-Bridge

- Drive motors
- forward / Backward

BJT

- Need BJT b/c Dragon Board does not output enough voltage for the H-Bridge

12/1/16
Pg 27

- worked on code
- used Tilt sensors
to control motors